

## Estimate of US\$2M for restoration

### DAMAGE SUSTAINED TO FACILITIES ACROSS THE CAMPUS TO INCLUDE:

1. Roofing membrane and structure
2. Windows and panels
3. Chain-link and perimeter fencing
4. Electrical infrastructure (poles and wires)
5. Student accommodation
6. Staff housing roof damage
7. Ceiling Damage
8. Water ingress
9. Flooding
10. Furniture and equipment damage

### HALLS OF RESIDENCE & STUDENT SUPPORT FACILITIES

- Elsa Leo Rhynie Hall
- Taylor Hall
- Chancellor Hall
- AZ Preston Hall
- Mary Seacole Hall
- Rex Nettleford Hall
- Marlene Hamilton Hall
- Students' Union Buildings

### FACULTIES AND DEPARTMENTS:

- FST Chemistry Department
- Faculty of Science and Technology
- Faculty of Humanities and Education - N-Block classrooms
- Faculty of Humanities and Education – School of Education
- Faculty of Science & Technology - Life Sciences Lecture Theatre
- Medical Sciences

- Administrative Buildings – (Principal’s Office and Bursary)
- Faculty of Law
- Social Sciences
- Faculty of Engineering

#### **COLLEGE COMMON STAFF HOUSING**

- Staff Housing

#### **GENERAL CUTTING AND CLEAN-UP OF CAMPUS**

- Tree Cutting and Clean-up
- Equipment and Trucking

#### **DISCOVERY BAY MARINE LAB**

- Dormitory Building
- Staff Flats Building

#### **WESTERN JAMAICA CAMPUS**

Severe roof damage:

- Main Administrative Building
- South Building (Director and Staff Offices, Classroom)
- 600 Block (Students Residence)